

SANBAG

San Bernardino Associated Governments Monthly Construction Report State Route 30/210

Construction through July 2001

PROJECT PHOTOS:

Segment 1: Forming of headwall and apron for Drainage System 2A.



Cucamonga Creek Channel: View of channel looking at the limits of demolition and new invert construction.



Cucamonga Creek Channel: View looking south at construction of walls and invert for the channel.



Segment 5: View looking east at the striping operation for opening of freeway in August 2001.

